

# HAN1100 Ultimate Addendum


It has come to our attention that two measurements listed in the Ultimate manual are incorrect. This addendum corrects this issue by providing the correct measurements for the axle location on the wheel pant and the centerline on the firewall.

Make the necessary changes in your manual before performing these steps.

## Page 42, Step 3

The measurement for locating the axle on the wheel pant is incorrect. The step should read as follows:

Measure and mark the location for the axle on the wheel pant. The center of the axle will be located  $5/8$ " up from the bottom of the pant. Drill the location using a  $1/2$ " drill.



## Page 56, Step 2

The photo for drawing the centerline on the firewall has the measurement referenced from the wrong side of the engine box. The correct wording and photo are as follows:

Draw a vertical and horizontal centerline on the firewall. The horizontal line is located  $2\frac{1}{2}$ " from the top of the firewall, and the vertical line  $3\frac{13}{16}$ " from the left side of the firewall, as viewed from the front.

